EENS Facility Risk Assessment

Name(s) of Rick T	nly official copy of this file is the o	ne on-line. Before using a printed copy, verify that	it is the	most	urrent v	version l	by checking t	he document issue d	ate on the	EEN	IS OH	SAS w	b site.	
Name(s) of Risk Team Members: P. Sullivan, D. Elling, L. Bowerman, T. Sullivan, J. Madaia			1			2	3	4			5			
Area/Facility Description Title: Building 487 Facility Risk Assessment FRA #: EENS- FRA-487 Rev.#: 2				≤once/year ≤once/		ce/month <pre><once <<="" pre="" week=""></once></pre>		≤once	once/shift		>once/shift			
Area/Facility Description: Bldg. 487 - Indoor and Outdoor Area			First Aid Medical Only Treatment				Partial I sability			Death or Permanent Disability				
Approved by: Date: 5/14/08 Linda Bowerman			Extremely Unlikely			Unlikely		Possible	Probable			Multiple		
Reason for Revision	on (if applicable):				. 45894.94C I			Comments:	<u> </u>		· <u> </u>	<u> </u>		- 101 - 101
				Risk with Controls in Place			1			Risk with Additional Controls in Place				
Physical Item or Activity	Hazard(s)	Control(s)	Occupancy A	Severity B	Likelihood C	Risk* AxBxC		ntrol(s) Added Reduce Risk		Occupancy A	Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction
General Facility Admin. Activities	General Administrative Building Hazards	See EENS-FRA-001	-	-	-	-	to Reduce Risk		Ye.					Reduction
General Facility Experimental Activities	General Experimental Building Hazards	See EENS-FRA-002	-	-	-	-			10					
Bldg. 487 Outdoor Area								· · · · · · · · · · · · · · · · · · ·					1.3	
Building perimeter	Slips, trips, falls on unpaved surface	Tier I Inspections, housekeeping	5	2	3	30		95	12/2 ha					
	Being struck by vehicle using bldg, perimeter as a turn around point	PPM turnaround proposed	5	5	2	50		afety contacted - mporarily used		5	5	1	25	50%
Building access	Delayed emergency response due to parked vehicles blocking egress	Tier I Inspections	5	5	2	50	Email sent to Line Manager & Building Manager for Records; "no parking" signs posted			5	5	1	25	50%
Bldg. 487 Indoor			-				posted				Ž.			
Working condition	Slips/trips/falls due to uneven surfaces	Tier I Inspections, housekeeping	5	2	-3	30								
	Temperature extremes	Propane heater; Tier I Inspections, fan, heat stress and weather alerts	5	2	1	10		1.000.00						

EENS Facility Risk Assessment

The only official copy of this file is the one on-line. Before using a printed copy, verify that			Risk with Controls in Place					Risk with Additional Controls in Place				,	
Physical Item or Activity	Hazard(s) Control(s)				Likelihood C	Risk* AxBxC	Control(s) Added to Reduce Risk	Occupancy A	Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction	
	Injury response (lack of landline phones& bldg. alarm)	Cell phone, Tier I Inspections	5	3	2	24	Landline telephone installed	5	3	1	15	50%	
	CO exposure	Roof vent	4	5	2	40	Monitoring performed - no exposure	4	5	1	20	50%	
	Fire hazard from propane heater	Proper use of propane heater, Tier I Inspections, landline telephone	5	3	1	15							
Further Description	of Controls Added to Redu				,	L	1	1 38	1	1 1	<u> </u>		
*Risk:	0 to 20 21 to 40		41-	60			61 to 80		8	81 or greater			
	Negligible	Acceptable	Moderate				Substantial			Intolerable			

Changes:

Rev. 1 - (Review Team Members: P. Sullivan, P. Carr, R. Doty, L. Bowerman, B. Bowerman, J. Madaia, B. Brown, D. Elling)

Editorial changes; Risks reduced: 1. "Injury Response" Hazard - clarification changed occupancy & severity based on actual hazards.

2. "CO Exposure" Hazard - monitoring reduced likelihood

Rev 2 - (Review Team Members: P. Philipsberg, S. Mitra, L. Wielopolski, L. Bowerman, J. Madaia)

Risks Reduced: 1. "Delayed emergency response due toblocked egress" hazard - no parking signs added to controls

2. "Injury Response" Hazard - corrected typographical error in Occupancy & Risk; landline line phone added to controls.

3. Modified hazard/controls and reduced risk in Indoor Working Conditions

Hazards Added: 1. Being struck by vehicle using building perimeter as turn around point

2. Fire Hazard from Propane Heater